

## SITE MONITORING REPORT

Please find detailed below the report for the site monitoring undertaken on 22<sup>nd</sup> May 2018. If you should have any queries or require any photographs taken on site please do not hesitate to contact me.

<b>File Ref:</b> 14 421 01		<b>Visit no:</b> 1 of 2	
<b>Monitoring Officer:</b> Tom McCarthy <b>Tel No:</b> 03330 320943		<b>Time on site:</b> 10:30	<b>Time off site:</b> 12:30
<b>Site Co-ordinator:</b> Tom McCarthy		<b>Tel No:</b> 03330 320943	
<b>Site Name:</b> Brightlingsea Quarry, Moverons Lane, Brightlingsea, Essex			
<b>Operator:</b> Brett Aggregates <b>Site Representative:</b> Chris Hemmingsley (Brett)			
<b>Permissions:</b> ESS/39/13/TEN – Winning and working of minerals with progressive infilling and restoration to agriculture and nature conservation (completion by 31/01/2026) – variation of ESS/61/12/TEN, ESS/28/03/TEN and ESS/47/94/TEN			
<b>Permission Number &amp; Romp Date Due:</b> ESS/39/13/TEN 04/07/2029			
<b>Constraints:</b>			
Weather:	<b>Dry</b> / Windy / Rain / Snow		
Noise:	<b>Acceptable</b> / Not acceptable / N/A		
Approach Roads:	<b>Dry</b> / Dusty / Wet / Muddy / Flooded		
Ground:	<b>Dry</b> / Dusty / Wet / Damp / Muddy / Flooded		
Access:	Obstructed / <b>Not Obstructed</b>		
Ground & Access Issues:	Mud on Road / Ice / Slippery / <b>N/A</b>		
Wheel Cleaning:	Washer / <b>Spinner</b> / Sweeper / None		
Hose:	In use / <b>Not in Use</b> / N/A		
Machinery:	<b>Working</b> / Not working		
In correct position:	<b>Yes</b> / No / N/A		
Stockpiles:	Height = <b>5m in processing area</b>		
Bunds:	Profiled / <b>Grassed</b> / <b>Weeds</b> / N/A		
<b>Actions from last site visit:</b>			
<ul style="list-style-type: none"> <li>• See Summary and Actions for update on condition submissions</li> </ul>			
<b>Inspection Results Summary:</b>			
<p>At the time visit no extraction was taking place, with only a limited reserve remaining in the existing Area C. Discussions are nevertheless still on-going between the operator and MPA in respect of archaeology in this Area and information to be provided following a previous breach of planning control.</p> <p>The internal haul road to Area B was clean and in a good state of repair. Infilling of Area B was taking place at the time of visit and had progressed significantly, since officers last visit, with the north-west corner approaching level.</p> <p>Limited works appeared to have occurred in Area A. Although the operator has started to form an access to the northern part of Area A so the restoration profile of the banks can be formed.</p> <p>Processing plant was operational at the time of visit.</p>			



Moverons Lane was generally clean, there was no significant surface damage on the approach roads and the footpath through the site was unobstructed.

<b>Compliance with Conditions</b>			
<b>Permission No.</b>	<b>Condition No.</b>	<b>Scope of Condition and Action to be taken</b>	<b>Action to be taken by Operator or MPA/WPA Officer</b>
ESS/39/13/TEN	9	Amount of waste deposited and void remaining during the last 12 months	Operator
ESS/39/13/TEN	16	Noise Monitoring	Operator
ESS/39/13/TEN	19	Planting Scheme	Operator
ESS/39/13/TEN	45	Aftercare Scheme	Operator
ESS/39/13/TEN	47	Biodiversity Mitigation and Enhancement Plan	Operator

**Permission under 2017 EIA regulations?: Yes / No**

**Actions to be taken before next site visit:**

An update is to be provided, by the operator, in respect of the outstanding conditions. It is understood that the operator has commissioned some ecological work which is delaying submission of details pursuant to conditions 19, 45 and 47. The MPA, in the circumstances, have agreed with the operator that a formal update is to be provided by the end of June 2018 – which it is expected will outline a timetable for submission of these outstanding schemes.

On-going dialogue with regard to archaeology in Area C is also expected.

**Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.**