

Site monitoring report

Please find detailed below the report for the site monitoring undertaken. If you should have any queries or require any photographs taken on site please do not hesitate to contact me.

Site Name: Pitsea Landfill, Pitsea Hall Lane, Pitsea, Basildon

File Ref: 32 421 02

Operator: Veolia& James Cook - Veolia

Site Representative: Mark Aspen

Visit no: 1 of 3

Date: 4 July 2023

Time on site: 14:30

Time off site: 16:30

Monitoring Officer: Claire Tomalin **Tel No:** 03330 136821

Site Co-ordinator: As above

Permission no's:

ESS/08/94/BAS, ESS/09/98/BAS, ESS/19/95/BAS – Offices, weighbridge

ESS/51/96/BAS, ESS/50/70/BAS, ESS/43/08/BAS, ESS/39/10/BAS - Landfill gas generation plant

ESS/92/97/BAS - Utilise landfill gas for electricity generation.

ESS/07/23/BAS and ESS/05/23/BAS - Green waste composting operation.

ESS/49/14/BAS - Landfill recontouring – main permission

ESS/06/23/BAS - Inert waste recycling for restoration materials

ESS/123/22/BAS– Storage tanks buildings etc

Constraints:

- Weather: Dry/ Windy / **Rain** / Snow
- Noise: **Acceptable**/ Not acceptable / N/A
- Approach roads: Dry / Dusty / **Wet** / Muddy / Flooded
- Ground: Dry / Dusty / Wet / **Damp** / Muddy / Flooded
- Access: Obstructed / **Not Obstructed** / Mud on Road / Ice / Slippery
- Wheel cleaning: **Washer** / Spinner / Sweeper / none N/A
- Hose: In use / Not in Use / **N/A**
- Machinery: Working / **Not working**
- In correct position: Yes / No / N/A
- Stockpiles: Height = **Acceptable**
- Bunds: Profiled / Grassed / Some weeds / **NA**

Inspection Results Summary:

Access road (Jul 2023)

No HGV movements observed during the visit.

Landfill

Due to lack of waste and restoration materials there had been no completion of further incomplete landfill cells since Oct 2022.

Green Waste Recycling – Visits Jan 2023

The green waste composting operation well managed – storage of processed material is the within building. Oversize processing has now moved to the area previously used for maturation of the IVC (now ceased operation). Oversize was being rescreened and blowing machinery used to remove plastics. An application will be needed to regularise this situation and this is in hand with James Cook of Veolia.

Compliance with Conditions:

ESS/49/14/BAS

Condition 19 prior to new areas being restoration details should be submitted in accordance with condition.

Condition 20 – a levels survey has identified areas of differential settlement resulting in slopes Veolia are concerned will lead to ingress of water to the cap.

Condition 21 – details of seeding for the next areas of restoration are required.

Condition 24 a Restoration Management Plan/Aftercare report was required to by May 2023 - outstanding.

Condition 28 Biodiversity Management Plan – was required to by May 2023 - outstanding. It may be that one Plan can address both Condition 24 and 28.

Condition 31 – cameras to observe wildlife need to be installed. Cameras in place, some footage but still trying to work out where to post on web. CT suggested approaching RSPB.

S106 obligation – a plan of action is required for removal of SRC, as MA explained likely to propose covering stumps with imported material, which will require pp.

S106 – submission of management plan for peripheral areas required by Nov 2022 - outstanding.

Actions to be progressed:

The requirements of the conditions/legal agreement above remain outstanding.

Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.