

# Site monitoring report

Please find detailed below the report for the site monitoring undertaken. If you should have any queries or require any photographs taken on site, please do not hesitate to contact me.

**Site Name:** St Clere's Hall Pit, Main Road, Danbury

**File Ref:** 23 421 16

**Operator:** Danbury Aggregates Limited

**Site Representative:** Dave Nurcombe (DN); Simon Chaffe (SC) – agent.

**Visit no:** 4 of 4

**Date:** 25/03/25

**Time on site:** 13:30

**Time off site:** 14:30

**Monitoring Officer:** T Burns (TB) Tel No: 03330136440

**Site Co-ordinator:** as above Tel No:

**Permission no's:**

**ESS/59/06/CHL** – Increase traffic movements

**ESS/63/10/CHL** – Infilling and Recycling

**ESS/12/13/CHL** – Western Extension.

**ESS/49/19/CHL** – Continuation of extraction.

**ESS/50/19/CHL** – Importation.

**Constraints:**

- Weather: combination **Dry**/ Windy / light Rain / Snow
- Noise

(as perceived by officer): **Acceptable**/ Not acceptable / N/A

- Approach roads: Combination of **Dry** / Dusty / Wet /Damp/ Muddy / Flooded
- Ground: **Combination of: Dry** / Dusty / Wet / **Damp** / **Muddy** / Flooded
- Access: Obstructed / **Not Obstructed** / Mud on Road / Ice / Slippery
- Wheel cleaning: Washer / Spinner / Sweeper / **Wheel bath available but not being used at time of visit.** /No/ N/A
- Hose: In use / **Not in Use** / N/A
- Machinery: **Working** / Not working (1 excavator in stockpiling area.
- In correct position: **Yes** / No / N/A
- Stockpiles: **Height = Acceptable**
- Bunds: **Profiled** / Grassed /Weeds / NA

#### **Actions from last site visit:**

- Addressing tree management/weed control aspects of the landscaping. **Update: No change from previous visit. Landscaping management/maintenance needs to be in place and being implemented first available season.**
- Clarifying programme for the void infilling/consultants actioning steps. **Update: Kept on as reminder once permit received for the operator to update on the infilling programme.**
- Stockpiles behind site offices growing in footprint and height. This is not a stocking area and heights will be breaching outside viewpoints. **Update: No action being taken by operator.**
- Clearance of the tree guards along western extensions southern perimeter. Removal where not required of the reptile exclusion fencing alongside the public footpath. **Update: DN advised that Tree guards cleared although fencing remains as required by ecologist.**

#### **Inspection Results Summary:**

- Site approach road and bellmouth mainly clean.
- Internal haul road was clean, no bowser in evidence at time of visit.
- Site operational with dozer on tipping area.
- Western extension land continues to establish with natural regeneration.
- As per last visit tree planting on bund alongside haul road between western extension and main site remains poor. Management arrangements for this and the western land area questioned. Previous weed growth continues to dominant.
- Stockpiling area behind site offices remains accommodating stockpiles (sands; crushed rubble/stone; soil making materials).
- Infilling platform extending further out into void. Fresh imported tipped material on surface of platform and forming 2-3 metre high periphery bund above slope.
- Appears infilling also evident on opposite eastern side of void where access track widened around rim of void and down into the void base. Turning square/stockpiling platform created off haul road outside void on eastern side with lifted soils placed in two main stockpiles between 2 -3 metres high. DN later confirmed that second

eastern most tipping exercise had resulted in slumping into lake of the tipped material and this exercise not suspended.

- Water levels in lake still high. Only remaining access track from rim of void down to water level is the eastern access arrangement.
- Processing plant area quiet. Stocks below conveyor arms; one larger gravel stock pile under the auxiliary plant and smaller ones under the main mobile plant. Also burnt out ADT parked up on northern boundary behind processing plant unit.
- As reported previously adjoining yellow hopper and two conveyor arms with gravel/stone stockpile of about 2/3 metres high. Behind was parked a red crusher unit.
- Across on eastern side was a hopper and sand/material stockpiles.
- Main stocking area continues to accommodate the perimeter stored old ballast mounds which have vegetation establishing on their surfaces. Northern perimeter mounds cleared of much of weed growth and comprises of newly tipped clay ready for lining purposes in void base. An amount of waste material referenced earlier in this report situated within the stocking area.
- 4 trailers and one derelict dump truck continue their presence parked on eastern side of stockpiling area above the lake.
- Crushing area quiet. Large amounts of rubble stocks present and presumably awaiting campaign crushing.
- The maintenance yard and surrounds continue to house their collection of some 20 plus cabs/trailers and full units accumulating as part derelict plant/parked HGV's that occupy the wider yard area.
- What appears to be a sump located on southern maintenance yard boundary appears to have been freshly accessed with tree removal and pushing back of ground levels by what looks like front loader bucket. Not sure reason for this disturbance.
- Use of land in the hollow for the activities taking place (storage/parking/processing) status remains on the reports as their activities will be affected with infilling activities taking place.

### **Compliance with Conditions:**

Permission/Condition No: ESS/63/10/CHL Conditions 13 (Noise); 24 and 25 (Soils notifications); 33 (Aftercare); 40 (Access alteration) and 41 (Removal of Structures)

Scope of Condition and Action to be taken: By operator within set timescales as set out in the permission.

Action to be taken by **Operator** or MPA/WPA:

Permission/Condition No: ESS/12/13/CHL Conditions 8 (Soil Placement notification); 13 (Lighting provision) and 15 (Aftercare scheme).

Scope of Condition and Action to be taken:

Action to be taken by Operator or MPA/WPA:

Permission/Condition No: ESS/49/19/CHL Conditions 7 (Ecological Interest); 8 (Great Crested Newts); 9 (Licensing); 10 (Protected Species); 17 (Noise Monitoring); 40 (Restoration) and 43 (Aftercare).

Scope of Condition and Action to be taken: As set out in permission.

Action to be taken by **Operator** or MPA/WPA:

**Permission under 2017 EIA regulations?:**

- Yes / **No**

**Proposed Mitigation Measures:**

- As per conditions

**Actions to be taken before next site visit:**

- Addressing tree management/weed control aspects of the landscaping.
- Clarifying programme for the void infilling/consultants actioning steps.
- Stockpiles behind site offices growing in footprint and height. This is not a stocking area. Revisions to working plan may be required to accommodate revised site layouts.
- Clearance of the tree guards along western extensions southern perimeter. Removal where not required of the reptile exclusion fencing alongside the public footpath.
- No further infilling across on eastern end of void. SC to look at working phase programme for the void.

Date of Next Meeting: 5<sup>th</sup> June 2025 @ 11:15 then onto Royal Oak

Date of Report: 25/03/25

**Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.**