

# Site monitoring report

Please find detailed below the report for the site monitoring undertaken. If you should have any queries or require any photographs taken on, please do not hesitate to contact me.

**Site Name:** Dunmow Waste Transfer Station, off Chelmsford Road, Great Dunmow, CM6 1LW

**File Ref:** 21 457 51

**Operator:** Veolia

**Site Representative:** Veolia

**Visit no:** 1 of 1

**Date:** Thursday 10th March 2022

**Time on site:** 12:15

**Time off site:** 12:30

**Monitoring Officer:** Tom Sycamore      Tel No: 03330 321 896

**Site Co-ordinator:** Tom Sycamore      Tel No: 03330 321 896

## Permission no's:

**ESS/18/12/UTT** – Change of use of land to a Waste Transfer Station to include the erection of a building for transfer/bulking of municipal and trade waste, together with ancillary development including dual weighbridge, office, staff welfare building, firewater holding tanks and pumphouse, underground surface water drainage tanks and pipework, package sewage treatment plant and pipework, vehicle wash system, staff car and cycle parking, vehicle hardstanding, fencing, improvements to the access road and associated works

**ESS/18/12/UTT/NMA1** – Amendments to approved landscaping scheme

**ESS/18/12/UTT/NMA2** – Installation of additional louvres

## Constraints:

- Weather:                      **Dry/ Windy / Rain / Snow**
- Noise:                         **Acceptable/ Not acceptable / N/A**
- Approach roads:           **Dry / Dusty / Wet / Muddy / Flooded**

- Ground: **Dry** / Dusty / Wet / Damp / Muddy / Flooded
- Access: Obstructed / **Not Obstructed** / Mud on Road / Ice / Slippery
- Wheel cleaning: Washer / Spinner / Sweeper / **Wash Bay**
- Hose: In use / Not in Use / **N/A**
- Machinery: **Working** / Not working
- In correct position: **Yes** / No / N/A
- Stockpiles: Height = **N/A**
- Bunds: Profiled / Grassed / Some weeds / **N/A**

**Actions from last site visit:**

- None.

**Inspection Results Summary:**

- The site was clean and clear of any debris or litter.
- Perimeter walk of the site carried out and no odour detected from outside the building, including to the rear of building near to residential receptors.
- Highway clear of debris.
- Weighbridge functioning well.
- Contractors in painting lines at time of visit.

**Actions to be taken before next site visit:**

- None.

**Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.**