

SITE MONITORING REPORT

Please find detailed below the report for the site monitoring undertaken on 24th September 2018. If you should have any queries or require any photographs taken on site please do not hesitate to contact me.

File Ref: 14 421 01		Visit no: 2 of 2	
Monitoring Officer: Tom McCarthy Tel No: 03330 320943		Time on site: 10:30	Time off site: 12:00
Site Co-ordinator: Tom McCarthy		Tel No: 03330 320943	
Site Name: Brightlingsea Quarry, Moverons Lane, Brightlingsea, Essex			
Operator: Brett Aggregates Site Representative: Simon Treacy, Angela Watt and Matthew Ball (Brett)			
Permissions: ESS/39/13/TEN – Winning and working of minerals with progressive infilling and restoration to agriculture and nature conservation (completion by 31/01/2026) – variation of ESS/61/12/TEN, ESS/28/03/TEN and ESS/47/94/TEN			
Permission Number & Romp Date Due: ESS/39/13/TEN 04/07/2029			
Constraints:			
Weather:	Dry / Windy / Rain / Snow		
Noise:	Acceptable / Not acceptable / N/A		
Approach Roads:	Dry / Dusty / Wet / Muddy / Flooded		
Ground:	Dry / Dusty / Wet / Damp / Muddy / Flooded		
Access:	Obstructed / Not Obstructed		
Ground & Access Issues:	Mud on Road / Ice / Slippery / N/A		
Wheel Cleaning:	Washer / Spinner / Sweeper / None		
Hose:	In use / Not in Use / N/A		
Machinery:	Working / Not working		
In correct position:	Yes / No / N/A		
Stockpiles:	Height = 5m in processing area		
Bunds:	Profiled / Grassed / Weeds / N/A		
Actions from last site visit:			
<ul style="list-style-type: none"> • See Summary and Actions for update on condition submissions 			
Inspection Results Summary:			
At the time of visit extraction was taking place of the remaining reserve (adjacent to the southern boundary) within Area C.			
The internal haul road to Area B was clean and in a good state of repair, although it was noted that water was pooling towards Area B rather than down the channels created towards Area A.			
Infilling of Area B was continuing and was progressing well.			
Processing plant was operational at the time of visit, with stockpiles circa 5m in height.			



Moverons Lane was generally clean, there was no significant surface damage on the approach roads and the footpath through the site was unobstructed. That said it was noted that the warning signs were missing where the footpath crosses the access point into Area C.

Compliance with Conditions			
Permission No.	Condition No.	Scope of Condition and Action to be taken	Action to be taken by Operator or MPA/WPA Officer
ESS/39/13/TEN	19	Planting Scheme	Operator
ESS/39/13/TEN	45	Aftercare Scheme	Operator
ESS/39/13/TEN	47	Biodiversity Mitigation and Enhancement Plan	Operator

Permission under 2017 EIA regulations?: Yes / No

Actions to be taken before next site visit:

Submissions in respect of conditions 9 (annual void survey) and 16 (noise monitoring), outstanding from the last monitoring report, were submitted and approved by the MPA in June 2018. Further noise monitoring is due February 2019.

With regard to conditions 19, 45 and 47 - an application for the approval of details pursuant to these conditions has been submitted and is currently being considered by the MPA.

On-going dialogue with regard to archaeology in Area C is expected in respect of the publication of findings. And, the operator is requested to review the PRow warning signage across the site.

Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.