

Site monitoring report

Please find detailed below the report for the site monitoring undertaken. If you should have any queries or require any photographs taken on, please do not hesitate to contact me.

Site Name: Alresford Creek

File Ref: 14 421 10

Operator: Brett Aggregates

Site Representatives: Karol Podkomorzy (Brett)

Visit no: 1 of 1

Date: Thursday 14th August 2025

Time on site: 11:10

Time off site: 11:40

Monitoring Officer: Tom Sycamore Tel No: 03330 321 896

Site Co-ordinator: Tom Sycamore Tel No: 03330 321 896

Permission no's:

ESS/72/24/TEN(R) – Postponement of periodic review of mineral permission (ROMP) ref: ESS/31/10/TEN R

ESS/31/10/TEN(R) - First periodic review of Old Minerals Permission reference IDO/TEN/11/92A

ROMP review date: ESS/72/24/TEN(R) - Review year 2035

Constraints:

Weather: Dry/ Windy / Rain / Snow

Noise: Acceptable/ Not acceptable / N/A

Approach roads: Dry / Dusty / Wet / Muddy / Flooded

Ground: Dry / Dusty / Wet / Damp / Muddy / Flooded

Access: Obstructed / Not Obstructed

Machinery: Working / Not working (excluding CBP)

• In correct position: Yes / No

Stockpiles: Height = Various

Bunds: Profiled / Grassed / Some weeds / NA

Actions from last site visit:

Site access road and associated signage maintained.

• Site and weighbridge office and weighbridge now removed from site.

Inspection Results Summary:

- Observed CBP in operation (separate permission from mineral operation).
- HGVs importing mineral to feed CBP. Single dozer transferring sand from stockpiles to CBP.
- Brett mixers leaving site to deliver produced concrete.
- Processing plant has not be operating since processing plant at Lufkins has been constructed and operated. Only processing taking place is 4-20mm to supply CBP.
- All CBP-related activities to cease and CBP to be mothballed once recently approved CBP at Lufkins is constructed and operational.
- Weighbridge and office has been removed from site and relocated to Lufkins.
- Storage area at western end of site empty with no material or plant currently stored.
- No reported issues from neighbours along haul road. All signage is in place along haul road advising drivers to slow down.
- ROMP (review of old mineral permission) has now been postponed until 2035.
 Permission lapses in 2042.

Permission under 2017 EIA regulations?:

Yes / No

Actions to be taken before next site visit:

Continue maintenance of site and access road.

Note: The actions noted in this report are required in order to ensure adequate progress is made and to avoid potential enforcement action against a breach of planning control.