

SITE MONITORING REPORT

Please find detailed below the report for the site monitoring undertaken on 25th February 2019. If you should have any queries or require any photographs taken on site please do not hesitate to contact me.

File Ref: 14.457/31		Visit no: 1	
Monitoring Officer: Tom McCarthy Tel No: 03330 320943		Time on site: 12:30	Time off site: 12:45
Site Co-ordinator: Tom McCarthy		Tel No: 03330 320943	
Site Name: A120 WTS, Former Truck Stop A120, Ardleigh, Colchester, CO7 7SL			
Operator: Veolia			
Permissions:			
ESS/16/13/TEN – Proposed development of a new waste management facility, with associated change of use of land. The facility comprises erection of a building for the transfer/bulking of municipal waste, together with ancillary development including dual weighbridge, weighbridge kiosk, office and staff welfare building, fire water holding tank and pumphouse, electricity substation, infiltration basin to manage surface waters and pipework, package sewage treatment plant, vehicle wash system, staff car parking, vehicle hardstanding, fencing, landscaping, formation of accesses to site and associated works			
ESS/16/13/TEN/NMA1 – Relocation of staff car park and addition of new chain-link gate			
ESS/27/16/TEN – Variation of condition 5 (noise monitoring)			
ESS/04/17/TEN – Variation of condition 2 (approved details) to allow overnight parking of associated HGVs			
Constraints:			
Weather:	Dry / Windy / Rain / Snow		
Noise:	Acceptable / Not acceptable / N/A		
Approach Roads:	Dry / Dusty / Wet / Muddy / Flooded		
Ground:	Dry / Dusty / Wet / Damp / Muddy / Flooded		
Access:	Obstructed / Not Obstructed / Mud on Road / Ice / Slippery		
Wheel Cleaning:	Washer / Spinner / Sweeper / Wash Bay		
Hose:	In use / Not in Use / N/A		
Facility/Machinery:	Operational / Not operational		
Stockpiles:	Height = N/A		
Bunds:	Profiled / Grassed / Weeds / N/A		
Inspection Results Summary:			
<ul style="list-style-type: none"> • Site clean and tidy. • Layout in accordance with planning permission and measures detailed in the odour mitigation scheme were in operation – traffic light system to the reception hall; and sensor detection fast acting roller shutter doors. No waste was stored outside the confines of the building. • Officer went within the building and noted materials stockpiled within. No significant odour nevertheless detected outside the building. • Highway clear of dirt and debris. 			
Actions to be taken before next site visit:			
N/A			

